

Valdese Public Safety Building Evaluation

Outline

Building Repairs and Accessibility
Building Renovations
Logistics
Operation Requirements
Comparison
Opinion of Probable Cost


Building Repairs and Accessibility

Wall Cracks Parapet **Exterior Doors** Police Upgrades Fire Sprinkler Floor Drainage Water Leaks Accessibility **Toilets** Entrance Exit Shower Elevator

Existing Building



Interior Masonry Wall Cracks



Interior Vertical Wall Cracks (Police)






Interior Horizontal Wall Cracks (Police)







Interior Vertical Wall Cracks (Police)






Interior Vertical Wall Cracks (Police)








Interior Wall Displacement (Police)

South Wall

Previous Horizontal Wall Crack Repair











Exterior Horizontal Wall Crack Repair


East Wall Cracks






East Wall Canopy/Cracks







North Wall Cracks







East Wall Parapet






Wall Crack Diagram







Wall Repair




Wall Repair



Replace Exterior Steel Doors & Frames




Fire Sprinkler




Full Building Coverage
Riser Controls
Backflow/Hotbox
Fire Water Service
Fire Alarm
Monitoring


Police Upgrade / CALEA Requirements

Commission on Accreditation for Law Enforcement Agencies







Building Renovations – Environmental Risk




Building Renovations – New Floor Drainage



Water Leak



Accessibility Renovation – Floor 1



Accessibility Renovation – Floor 2



Replace Exterior Building Sign

Police & Fire Kitchen Renovation (Shared Space)

HVAC (Obsolete / Maintenance)

Plumbing (Maintenance)







Upgrade Electrical (Power & Lighting)
Upgrade Life Safety Exit & Egress Lighting
Emergency Back-up Power Generator (Partial)



Steel Bracing Frames (Category 4 Essential Facility)

Asbestos Abatement
Interior Finishes (Floors, Walls, Ceilings)









Apparatus Bay Floor Finish
Apparatus Bay Vehicle Exhaust System
Replace Existing Windows
Police & Fire Office Renovations






Relocation During Renovation

Phase Renovation to Reduce Relocation

Logistics



Operational Requirements

Overview of Existing Facility Problems

The 42-year-old & 95-year-old buildings are overcrowded and do not support efficient or safe fire and police operations.
These problems compromise ability for services to be delivered to the public in a safe, secure, and efficient manner.
Many functions are required to share small & crowded spaces.
There is <i>limited opportunity</i> for internal training, community activities, and many other functions.
The building in question is a combination of three structures. Cracks are present in most exterior walls. Cracks seem to be worse in the 1978 addition (police) and moving towards the fire department, but <i>the entire structure is compromised</i> .
Instead of there being a single storage area, items are <i>separated into several small storage areas</i> . SCBA compressor, gear storage, are ice machine are located within the Apparatus Bay. <i>Truck exhaust creates risk for contamination</i> .
Turn-out gear storage within Apparatus Bay. Truck exhaust creates hazardous contaminants.
Lack of sufficient areas for Storage Support is <i>forcing the diversion of some Apparatus equipment, materials and supplies to improvised locations, impairing operational efficiency.</i>
The Fire & Police Departments do not have a Fitness/Exercise area. Employees must leave the station to travel to a gym. The public gym is not always open during times that firefighters can attend and does not have after hours access.
There is very little hands-on training that can be completed at existing building.

Overview of Existing Facility Problems

The Dayroom is only big enough for two people so when extra personnel are on duty there is not room. <i>This does not support efficier fire and police operations.</i>
The <i>Fire Sleeping area is too far away from the bays and located on a second level.</i> The existing facility has <i>one large sleeping area</i> which is not ideal when you have a <i>combination of female and male employees</i> . Only one bathroom and shower in the sleeping area
Lockers are insufficient in number and size.
The Administration offices are small and spread in the facility.
One workstation for all the Patrol officers and is not sufficient.
Storage space which it located in the different building.
Administrative support lacks space for conference room, interview rooms, supply storage, file cabinets, copy machine.
Patrol functions lack needed grouping for operational efficiency.
The existing Police facility lacks Report Writing space.

Overview of Existing Facility Problems

The existing Police do not have a dedicated Roll Call room. Spaces are not large enough for all personnel involved in shift briefings.
Police Training is conducted off-site. Certain training needs are better conducted in-house.
The Police Department lacks a Locker Room with sufficient space to accommodate officer uniforms, personnel equipment, boots, and other needed items.
The Police Department do not have an arrestee Processing/Holding area.
Absence of a Sallyport for prisoner transfer at the Police facility is brings with it a serious security risk.
Evidence Storage is overly congested and operationally inefficient due to the existing building space. Evidence storage with sensitive evidence items is accessed from the Break Room, and some evidence lockers are located in the Break room due to the lack of space.
Evidence Storage and evidence related areas lack Pass-through lockers, Bag and Tag area, separation of the Drug, Valuable, Weapon storage. Evidence Storage has no logging system.
Break Room is too small and lacking in needed features, i.e., sink, oven, dishwasher, microwave, refrigerator, icemaker, and sufficient vending machines. All these features are presently located in the Kitchen on the Fire Department side. It is very insufficient in location for required access and in needed features.

Overview of Existing Facility Problems

The entire Fingerprint and photo ID area lack secured separation from civilian use.
Central location is needed for printer, copier, scanners, fax, and shredder.
Storage areas are located outside of the building, and this restricts access on a daily basis. Each Police Department unit requires storage for different purposes. Among the needs are archival storage, equipment/supplies.
Functionality of the Records Division is to work as a large open space with individual work areas. Administrative Assistant serves two Departments Police and Fire. Existing support areas currently in dire need additional space with no means for expansions in the present building configuration.
Lobby is overly congested and operationally inefficient due to the existing building space availability and configuration.
Rear of the police department is unsecure in the parking lot. Anyone can enter Police Parking lot in the rear of the department. Police employees must enter through traffic into the parking lot even though there are signs. Officers cannot see if anyone is outside the door before exiting the building. The rear door has no way of observing what or who is on the other side. No camera system is in place. No surveillance ability is provided. Police parking does not have a secure fenced parking lot.


Comparison

		Existing	20 Year	Schematic
		Building	Need	Plan
A. Poli	ce Department			
A1	Adminstrative	385	722	787
A2	Records	360	339	272
A3	Investigations	0	103	147
A4	Patrol	588	772	907
A5	Break Room	205	200	240
A6	Intake / Holding	139	638	508
A7	Sallyport	0	880	900
A8	Property / Evidence	153	480	526
A9	Locker Rooms	0	550	577
A10	Storage	544	680	518
R Fire	Department		-	
B1	Adminstration	680	960	891
B2	Operations - Work Area	73	150	160
ВЗ	Operations - Support Areas	924	1390	1397
B4	Locker Rooms / Toilets	495	538	515
B5	Apparatus Bay	3374	6400	6400
B6	Support Storage	1360	1406	1939
C. Sha	red Areas	-	-	
C1	Lobby	290	712	536
C2	Training Room	485	1754	1217
C3	Fitness	0	750	424
D. Sub	ototal	10055	19424	18861
E. Dep	t. & Building Grossing Factor	6763	6960	5621
	Includes departmental & building circulation,			
	mechanical & electrical areas, building	- 1		
	structure, and exterior envelope.		L.,	
F. Tota	al Gross Square Footage	16818	26384	24482
		Defficient	(9566)	(7664)
			-36%	-31%

Comparison


>30% Deficient

Building Comparison




Existing 16,818 sf (7644 sf)

Second Floor



First Floor











Gender Separation

Separate Bunk Room & Locker Room




Gender Separation

Separate Bunk Room & Locker Room




First Floor




Security Safety Risk

Existing Police Processing

Proposed New Facility







Reduce Risk:


Secure Processing & Holding

Second Floor



First Floor





Health Risk:

Existing Condition

Vehicle Exhaust Contamination












Proposed New Facility



Proposed New Facility – Isolated Storage




Existing Facility – Fire Truck Bays



- (2) drive thru bay (15'-0" x 70'-0")
- (2) back-in bays
- Store (7) vehicles
- Limited Flexibility (30'-0" x 70'-0")
- Retrofit Vehicle Exhaust & Ventilation
- Storage remote from Bay


Proposed New Facility – Fire Truck Bays



- (4) drive thru bay (20'-0" x 80'-0")
- (8) back-in bays
- Store (8) vehicles & (1) trailer
- Greater Flexibility (80'-0" x 80'-0")
- Equipped w/ Vehicle Exhaust & Ventilation
- Storage adjacent to Bay
- Tilt Cab

Opinion of Probable Cost of Construction

Existing Building - Opinion of Probable Cost




16,818 sf \$6,484,199

Renovation Cost

Soft Cost
Furnishing & Equipment
Temporary Structure Cost (Relocation)
Includes NC State Grant

New Building – Opinion of Probable Cost



24,500 sf \$7,048,050

Building Cost
Site Development Cost
Soft Cost
Furnishing & Equipment
Includes NC State Grant

Thank you for your time.